

राँची नगर निगम, राँची।

Ref: 195/Health Sec

Date: 11/09/2026

I inspected DAV Nageshwar Public School, At Chandaghasi, Tetri, Ranchi - 834010 (Jharkhand) on 02-09-2026

The following conditions were observed in the school:

1. Building Safety :-

Found Satisfactory Railing and parapet walls up to height of 3'-00" have been provided in corridors, balconies, and staircase and roof top. Safety grills have been provided in windows and other openings.

2. Fire safety :-

Fire extinguishers are available in sufficient numbers.

3. Drinking water facility :-

Having pump and silent generator in addition to the electric power supply to lift the water from deep well to store in the overhead water tanks. Sufficient nos. of water taps connected with water purifier and over head tanks to provide suitably for drinking water, gardening and in toilets.

4. Health and Sanitary conditions :-

Two septic tanks with soak pit have been built to accommodate adequate nos. of water closets and urinals. Pucca drains has also been provided. Separate toilets have been provided for boys and girls.

Overall the facilities mentioned above in the school building and campus are found in good conditions.

K. S. Kumari
11/09/2026

स्वा० चिकित्सा पदाधिकारी

सहा० लो० स्वा० पदा०

राँची नगर निगम, राँची